


## 2301-220/C, 1000, 1, CINCH

SN168C



PT1000 -30 to +220°C.

-30 to +220°C, CINCH.

.

t63 < 10s, t95 < 30s